



Per the Hyundai service information: "Never attempt to modify, splice, or repair SRS wiring. If there is an open or damage to the SRS wiring, replace the harness."