



Per Kia service manual: "SRS wiring can be identified by special yellow outer covering. Observe the instructions described in this section. Never attempt to modify, splice, or repair SRS wiring. If there is an open or damage in SRS wiring, replace the harness."