



# **MITSUBISHI MOTORS**

Mitsubishi

Per the Mitsubishi service information: "Do not attempt to repair the wiring harness connectors of the SRS. If any of the connectors are diagnosed as faulty, replace the wiring harness. If the wires are diagnosed as faulty, replace or repair the wiring harness according to the following table." The table can be found in the Mitsubishi repair information.