



Nissan / Infiniti

Per the Nissan and Infiniti service information: "DO NOT Attempt to repair, splice or modify the SRS wiring harness. If the harness is damaged, replace it with a new one."