



# Mercedes-Benz

Mercedes-Benz / Smart

Per the Mercedes-Benz service information: "The SRS wire harness pigtail is replaced using solder connectors. Contact a Mercedes-Benz part dealer."